

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

*Asst. Executive Engineer
Vasudevanthi Public School
Adimidi (Sub. dis.) Thodupuzha
(Dist.)*

1. Name of the Officer
2. Name of the School
3. Location with name of Education District/ Sub. District
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.

LP section G+2 - 67.30x9.40x11.50 m
UP G+2 - 39.40x11.20x11.50 m
KG section G+2 - 67.90x12.20x11.50 m
HS G+3 - 74.40x9.10x15.50 m
R.C.C framed structure with 50 No. of class rooms of size 7.00x6.00x3.60m.

5. Period for which the certificate is issued

6. Nature of defects, if any

a) Foundation and basement

b) Superstructure

c) Doors and Windows

d) Wood work wrought and put up

e) Roof

f) Flooring

g) Miscellaneous (Cracks, etc.)

Nil.

Nil

7. Any major defects noticed which will render the building unsafe in any manner

NO.

8. Whether maintenance works have been done properly

Yes.

9. Whether the structure is sound or not for conducting classes

Yes.


Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

certified that the school building was inspected by me on 23.04.2024 and found to be fit / unfit to conduct classes, for the period of one year for the reasons stated above. subject to the conditions in letter no. AEE/LSG/ADLY/04/24 dt 23.04.24 and the affidavit submitted by you in response

Place: Adimidi

Date: 24.04.24



[Handwritten signature]
 Assistant Executive Engineer